



Repair Order

Invoice

Doc Number: 13583

Service Writer: RANDY ERICKSON

Date Printed: 05/15/2025 Date Promised: 07/21/2022 Date In: 07/21/2022

Cashier: JENNA HOBAN
Cashier Date: 09/19/2023

Customer Information

Home Phone:
Cell Phone:

Email:

Summary

prove Decline Unit Job	Job Total
2021 SEA DOO 2UP SPARK TRIXX W/ HOLE IN HULL	\$3,748.01
2021 SEA DOO 2UP SPARK TRIXX W/ WINTERIZE PWC	\$133.30
☐ 2023 SEA DOO 65PA TRAILER	\$0.00
	Job Subtotal: \$3,881.31
	Misc: \$51.00
	Job Parts Subtotal: \$1,461.76
	Job Labor Subtotal: \$2,419.55
	Tax: \$107.80
	Total: \$4,040.11
	Less Deposits: \$0.00
	Check(6004014165): (\$4,040.11)
	Total Due: \$0.00

LEFT VOICEMAIL LETTING CUSTOMER KNOW PARTS ARE HERE KLS 04-11-2023 NEED TO LAKE TEST

CUSTOMER SAID HE IS GOING TO FILE AN INSURANCE CLAIM - 8/22/23 JH

THANK YOU FOR YOUR BUSINESS! SERVICE PROBLEMS MUST BE REPORTED WITHIN 10 DAYS OR 100 MILES. WARRANTY COVERS 30 DAYS OR 100 MILES WHICH EVER COMES FIRST NO EXCEPTIONS!!! 30 DAY WARRANTY DOES NOT APPLY TO COMPETITION RACE MODELS. ASK US ABOUT OUR WINTERIZING SPECIALS. WHEN NEW TIRES ARE INSTALLED ON YOUR BIKE BE CAREFUL, YOUR FIRST 100 MILES YOUR TIRES ARE SLIPPERY. COMPONENTS WHICH AFFECT EMISSIONS ARE FOR CLOSED-COURSE RACE

Signature:		
Jigiiatai C.		

Detail

2021 SEA DOO 2UP SPARK TRIXX W/ SOUND Unit

65ME

Color: Keyboard:

VIN/Serial No:YDV60981C121 Plate: Odom/Hrs In:0 Out:0

HOLE IN HULL

Description: NEEDS HULL REPLACEMENT

PERFORM OIL CHANGE (NEEDED WITH HULL CHANGE)

Р	ar	ts
---	----	----

Part #	Qty	Description	Price	Discount	Total
295501188	1.00	HULL	\$949.99	\$0.00	\$949.99
268000208	1.00	GASKET	\$14.49	\$0.00	\$14.49
414115200	4.00	TIE-RAP 180 MM	\$0.10	\$0.00	\$0.40
293750049	1.00	WRAP_TIE 305 X 4.6	\$2.09	\$0.00	\$2.09
293750008	1.00	TIE-RAP 350MM	\$0.98	\$0.00	\$0.98
250001007	13.00	SCREW-PLASTITE TORX CONE HD.M6	\$2.29	\$0.00	\$29.77
509000181	1.00	GEAR CLAMP	\$4.19	\$0.00	\$4.19
293650099	1.00	CLAMP	\$4.19	\$0.00	\$4.19
293300006	1.00	O-RING	\$4.19	\$0.00	\$4.19
279000336	10.00	FLAT WASHER	\$9.69	\$0.00	\$96.90
271001958	1.00	GASKET	\$22.49	\$0.00	\$22.49
207382560	1.00	SCREW	\$2.29	\$0.00	\$2.29
277001977	1.00	RUBBER GASKET	\$2.39	\$0.00	\$2.39
509000529	1.00	CRIMP CLAMP	\$8.99	\$0.00	\$8.99
779150	3.00	COOLANT EXTENDED LIFE PREMIXED	\$10.99	\$0.00	\$32.97
420956123	1.00	FILTER-OIL	\$10.99	\$0.00	\$10.99
779136B	6.00	OIL 4T 5W40 SYNTH. BLEND 55 GA	\$16.99	\$0.00	\$101.94
CR8EB	3.00	SPARK PLUG CR8EB	\$7.69	\$0.00	\$23.07
234082600	1.00	WASHER-FLAT DIN.9021	\$2.29	\$0.00	\$2.29
295501209	1.00	ROTARY RING KIT	\$92.99	\$0.00	\$92.99
219905757	1.00	FRONT LEFT HULL DECAL	\$18.49	\$0.00	\$18.49
219905758	1.00	FRONT RIGHT HULL DECAL	\$18.49	\$0.00	\$18.49
420956123	1.00	FILTER-OIL	\$12.99	\$0.00	\$12.99
250000827	1.00	SCREW-TORX TRUSS CONE HD.M6X50	\$4.19	\$0.00	\$4.19

Labor			
Description	Technician	Hours	Total
REPLACE HULL	JUSTIN SHARP	14.75	\$2,286.25
		Labor Subtotal	\$2,286.25
		Job Subtotal	\$3,748.01
		Approve: ☑	Decline: □

WINTERIZE PWC

Description:WINTERIZE SEADOO PWC

Lahor

Laboi			
Description	Technician	Hours	Total
WINTERIZE SEADOO PWC	JUSTIN SHARP	0.86	\$133.30
		Labor Subtotal	\$133.30
		Job Subtotal	\$133.30

Decline:

Approve: ☑

Parts Subtotal

\$1,461.76

2023 SEA DOO 65PA PWC SPARK TRIXX 90 Unit

GN 2UP IBR 23

Color: Keyboard:

Odom/Hrs In:0 VIN/Serial No:YDV22402J223 Plate: Out:0

TRAILER

Description: CUSTOMER WOULD LIKE UNITS ON A TWO PLACE TRAILER

Job Subtotal	\$0.00
Approve: 🗹	Decline: □
All Jobs Subtotal:	\$3,881.31
Shop Supplies:	\$51.00
Tax:	\$107.80
Total:	\$4,040.11
Less Deposits:	\$0.00
Check(6004014165):	(\$4,040.11)
Total Due:	\$0.00